No.: 3/2013

Telephone No.: (852) 2852 3001

E-mail: hkmpd@mardep.gov.hk Web site: http://www.mardep.gov.hk

Fax No. : (852) 2544 9241 Telex No. : 64553 MARHQ HX



## 香港商船資訊

## HONG KONG MERCHANT SHIPPING INFORMATION NOTE

## **Unified Interpretations of SOLAS Chapter V**

To: Shipowners, Ship Managers, Ship Operators, Ship Masters, Classification Societies and Shipbuilders

## Summary

The purpose of this Note is to promulgate the revised unified interpretations of SOLAS Chapter V on Regulation V/22.1.6 – Navigation bridge visibility.

- 1. The Maritime Safety Committee (MSC) of the International Maritime Organization (IMO) at its 91<sup>st</sup> session in November 2012, approved the circular MSC.1/Circ.1350/Rev.1 on unified interpretations of SOLAS Chapter V. The revised unified interpretations provide more specific guidance for vague expressions such as "The ship's side shall be visible from the bridge wing", which are open to different interpretations contained in IMO instruments.
- 2. The details of the unified interpretations can be found as attachment to this Note on the website of Marine Department (http://www.mardep.gov.hk/en/msnote/msin.html).
- 3. Shipowners, Ship Managers, Ship Operators, Ship Masters, Classification Societies and Shipbuilders of Hong Kong registered ships are required to use the annexed unified interpretations as guidance when applying relevant provisions of SOLAS chapter V to ships contracted for construction on or after 1 January 2011.

Marine Department Multi-lateral Policy Division

14 January 2013