No.: 44/2013

Telephone No. : (852) 2852 3001 Fax No. : (852) 2544 9241

Web site: http://www.mardep.gov.hk

Telex No.: 64553 MARHQ HX

E-mail: hkmpd@mardep.gov.hk



香港商船資訊

HONG KONG MERCHANT SHIPPING INFORMATION NOTE

Unified Interpretation of SOLAS Chapter II-1/26.3

To: Shipowners, Ship Managers, Ship Operators, Ship Masters, Classification Societies and Shipbuilders

Summary

The purpose of this Note is to promulgate the unified interpretation of SOLAS Chapter II-1/26.3 regarding the arrangement of fuel pumps to provide sufficient capacity for normal operation of propulsion machinery.

- 1. The Maritime Safety Committee (MSC) of the International Maritime Organization (IMO), at its 92nd session in June 2013, approved the unified interpretation of SOLAS Chapter II-1/26.3, regarding the arrangement of fuel pumps to provide sufficient capacity for normal operation of propulsion machinery even if one pump becomes inoperable, while using marine fuels with a sulphur content not exceeding 0.1 per cent/m/m and minimum viscosity of 2 cSt as required in Emission Control Areas from 1 January 2015.
- 2. The details of this unified interpretation as annexed to IMO circular MSC.1/Circ.1467 can be found in the attachment to this Note on the website of Marine Department (http://www.mardep.gov.hk/en/msnote/msin.html).
- 3. Shipowners, ship managers, ship operators, ship masters, classification societies and shipbuilders of Hong Kong registered ships are required to use this unified interpretation when applying the requirements of SOLAS regulation II-1/26.3.

Marine Department Multi-lateral Policy Division

8 October 2013