

MARINE DEPARTMENT NOTICE NO. 10 OF 2010

(Marine Works)

Submarine Outfall Inspection Works off Pillar Point, Urmston Road

With effect from 25 January 2010 and for a period of approximately two weeks, submarine outfall inspection works will be carried out off Pillar Point, Urmston Road, in the following areas:

Area 1: This area is bounded by straight lines joining the following co-ordinates (WGS 84 Datum) from (A) to (D):

(A)	22° 20.897'N	113° 55.973'E
(B)	22° 21.308'N	113° 56.184'E
(C)	22° 21.285'N	113° 56.237'E
(D)	22° 20.874'N	113° 56.026'E

Area 2: This area is bounded by straight lines joining the following co-ordinates (WGS 84 Datum) from (E) to (H):

(E)	22° 21.554'N	113° 56.310'E
(F)	22° 21.627'N	113° 56.348'E
(G)	22° 21.603'N	113° 56.401'E
(H)	22° 21.530'N	113° 56.363'E

2. One motor boat will carry out the works. One guard boat will provide assistance.

3. A working area of approximately 25 metres around the motor boat will be established. The hours of work will be from 0800 to 1700 hours. The vessels employed for the works will not stay in the works areas outside the hours of work.


4. Diving operations will be carried out from time to time during the hours of work.

5. Vessels engaged in the works will display signals as prescribed in international and local regulations.
6. Vessels navigating in the vicinity should proceed with caution and keep clear at slow speed, bearing in mind there are divers working in the areas.
7. A drawing showing the works areas is attached to this Notice.

H. P. LIU
Director of Marine (Ag.)

Marine Department
Government of the HKSAR
Date : 25 January 2010
Action File Ref. : L/M 2/10 in PA/S 915/11/42

海事處佈告 2010 年第 10 號附圖
Drawing Attached to Marine Department Notice No. 10 of 2010



不宜作航行用途
NOT TO BE USED FOR NAVIGATION