

Ships detained in Hong Kong by PSC Section in July 2013

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	8823317	PEACE	Cambodia	1988	1490	General cargo/ multipurpose	Union Bureau of Shipping	Union Bureau of Shipping	Huawei Shipping Co Ltd	02/07/13	18/07/13	CERTIFICATE AND DOCUMENTATION - CREW CERTIFICATES: certificate for rating for watchkeeping/short of one (1) watch keeping deck rating as per minimum safe manning certificate; FIRE SAFETY: fire pumps and its pipes/the only one fire hydrant in engine room damaged, number of hydrant in engine room to be verified, fire pumps and its pipes/fire pump suction pipe leakage causing fire pump inoperable, fire pumps and its pipes/emergency fire pump failed to delivery any water, ventilation/engine room ventilators (port) seized and failed to close; POLLUTION PREVENTION - MARPOL ANNEX I: oil filtering equipment/crew failed to start oily water separator; WATER/WEATHERTIGHT CONDITIONS: doors/forecastle store weathertight door rubber packing and securing handle damaged; LIFE SAVING APPLIANCES: launching arrangements for rescue boats/rescue boat davit driving motor not working; EMERGENCY SYSTEMS: emergency, lighting, batteries and switches/emergency source of power failed to supply emergency lighting

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.