No.: **28/2012** 

Telephone No. : (852) 2852 3001 Fax No. : (852) 2544 9241 Telex No. : 64553 MARHQ HX

E-mail: hkmpd@mardep.gov.hk Web site: http://www.mardep.gov.hk



## 香港商船資訊

## HONG KONG MERCHANT SHIPPING INFORMATION NOTE

## Unified Interpretations of SOLAS Regulation II-2/21.4

To: Shipowners, Ship Managers, Ship Operators, Ship Masters, Classification Societies and Shipbuilders

## **Summary**

The purpose of this Note is to promulgate the unified interpretations of SOLAS Regulation II-2/21.4 on the assessment of passenger ship systems' capabilities after a fire or flooding casualty.

- 1. The Maritime Safety Committee (MSC) of the International Maritime Organization (IMO) at its 90<sup>th</sup> session in May 2012, approved a circular MSC.1/Circ.1437 on unified interpretations of SOLAS Regulation II-2/21.4. The unified interpretations should be used as guidance when applying the relevant provisions of SOLAS Regulation II-2/21.
- 2. The details of the unified interpretations can be found as attachment to this Note on the website of Marine Department (http://www.mardep.gov.hk/en/msnote/msin.html).
- 3. Shipowners, ship managers, ship operators, ship masters, classification societies and shipbuilders of Hong Kong registered ships are required to note the unified interpretations and act accordingly.

Marine Department Multi-lateral Policy Division

28 June 2012