

**MARINE DEPARTMENT NOTICE NO. 21/2021**

(Establishment, Withdrawal and Changes of Aids to Navigation,  
Fairways, Anchorages & Other Port Facilities)

**Reinstatement of Lateral Mark Buoys**  
**Inside Causeway Bay Typhoon Shelter**

NOTICE IS HEREBY GIVEN that seven lateral mark buoys have been reinstated in the following positions (WGS 84 Datum) G1, G3, G7, R2, R4, R6 and R8 inside Causeway Bay Typhoon Shelter for marking the passage area. Particulars of the buoys are as follows:

<b><u>Name</u></b>	<b><u>Position</u></b>		<b><u>Shape</u></b>	<b><u>Colour</u></b>
G1	22° 17.170'N	114° 11.248'E	Conical	Green
G3	22° 17.121'N	114° 11.202'E	Conical	Green
G7	22° 17.115'N	114° 11.044'E	Conical	Green
R2	22° 17.151'N	114° 11.247'E	Can	Red
R4	22° 17.105'N	114° 11.203'E	Can	Red
R6	22° 17.080'N	114° 11.120'E	Can	Red
R8	22° 17.103'N	114° 11.044'E	Can	Red

2. A drawing showing the positions of the buoys is attached to this Notice.

**Agnes WONG**  
**Director of Marine**

Marine Department


Government of the HKSAR

Date: 21 January 2021

Action File Ref.: L/M. No. 1/21 in MD-PD&PS-F01-075-01A-001A-P005

海事處佈告第 21 / 2021 號附圖

Drawing Attached to Marine Department Notice No. 21/2021



不宜作航行用途

NOT TO BE USED FOR NAVIGATION