

Ships detained in Hong Kong by PSC Section in Aug 2015

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9342243	SUN ISLAND	Panama	2005	7104	General Cargo	Nippon Kaiji Kyokai	Nippon Kaiji Kyokai	Yokohama Marine & Merchant Corp	05/08/15	07/08/15	RADIO COMMUNICATIONS: MF/HF RADIO INSTALLATION RADIO MF/HF ANTENNA INSULATOR BROKEN AND HF DSC TEST UNABLE TO RECEIVE COST STATION; FIRE SAFETY: OIL ACCUMULATION IN ENGINE ROOM M/E LEAKING OIL (DARK OIL) IN VARIOUS PARTS OF M/E HIGH FIRE RISK. ISM: AS PER DEFICIENCIES ABOVE, MAINTENANCE OF THE VESSEL AND SMS ARE NOT IMPLEMENTED EFFECTIVELY AS PER ISM CODE
2	9546306	DONG CHENG 7	Jamaica	2008	2926	General Cargo	Isthmus Bureau of Shipping, S.A.	Isthmus Bureau of Shipping, S.A.	East Bright International Shipping Ltd	05/08/15	06/08/15	WATER/WEATHERTIGHT CONDITIONS: CARGO & OTHER HATCHWAYS SMALL HATCH FOR THE ENTRANCE OF BOSON STORE AT FORWARD MOORING STATION CANNOT BE CLOSED PROPERLY; FIRE SAFETY: OIL ACCUMULATION IN ENGINE ROOM E/R OILY BILGE WELL (AFT)
3	8743749	YONG JUN 17	Sierra Leone	2008	2967	General cargo	Sing-Lloyd	Union Bureau of Shipping	Hong Kong Yongli Shipping Co Ltd	06/08/15	11/08/15	RADIO COMMUNICATIONS: MF/HF RADIO INSTALLATION MF/HF RADIO ANTENNA DAMAGED AND SYSTEM FOR SHIP-SHORE TEST FAILED; FIRE SAFETY: FIRE DETECTION AND ALARM SYSTEM FIRE DETECTION SYSTEM DEFECTIVE WITH FAULT ALARM; ISM: OTHER (ISM) AS PER EVIDENCES ABOVE, SMS ON BOARD NOT IMPLEMENTED EFFECTIVELY; SAFETY OF NAVIGATION: VOYAGE OR PASSAGE PLAN VOYAGE PLAN FOR LAST VOYAGE, NOT ENSURED TO USE UPDATED CHARTS AND INCLUDED VOYAGE PLAN BERTH TO BERTH, ESSENTIAL INFORMATION FOR SAFE NAVIGATION AND PASSAGE MONITORING, UNAPPROVED ECS WAS TURNED ON IN PORT; SAFETY OF NAVIGATION: LIGHTS, SHAPES, SOUND-SIGNALS SHIPS AIR HORN CONTROL WIRE DEFECTIVE/ BROKEN
4	9517020	YUN SHENG	Cambodia	2007	5702	General cargo/multipurpose	Union Bureau of Shipping	Union Bureau of Shipping	Hao Liang Yun Shipping Co Ltd	18/08/15	24/08/15	ISM: Other (ISM) SMS AS IMPLEMENTED DOES NOT ENSURE MAINTENANCE OF THE SHIP, SHIP BOARD OPERATIONS EFFECTLY; SAFETY OF NAVIGATION: Charts BA CHARTS 4127, 937, 4129 NOT UPDATED/OBSOLETE EDITION. POSITION FIX RECORD NOT AVAILABLE ON PAPER CHARTS AND USE UNAPPROVED ECS FOR NAVIGATION, CHART CATALOGUE NOT UPDATED.

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.