

Ships detained in Hong Kong by PSC Section in January 2016

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9167461	KANWAY GLOBAL	TAIWAN, CHINA	1997	18502	CONTAINER	CRCS	CRCS	CHINA FAMOUS CO. LTD.	2016 01 06	2016 01 19	LIFE SAVING APPLIANCES: LIFEBOAT (PORT) STEERING DEFECTIVE, EMERGENCY SYSTEMS: EMERGENCY FIRE PUMP DEFECTIVE/UNABLE TO DELIVER WATER, WATER/WEATHER TIGHT CONDITIONS: NUMEROUS CARGO HATCH COVERS DAMAGED AND UNABLE TO CLOSED WEATHER TIGHT (INCLUDING EDGES, POSITION GUARDS, ETC.) AND CRACKED/HOLED., ISM: FROM THE EVIDENCES ABOVE (ITEMS 1-24) SAFETY MANAGEMENT ONBOARD NOT EFFECTIVELY IMPLEMENTED..
2	8663781	HOI TAI	HONDURAS	2003	2989	CONTAINER	C.T.M.	C.T.M.	SHUN TIN TRADING CO LTD	2016 01 13	2016 02 01	FIRE SAFETY: "B.P. FAULT" SHOWN ON THE FIRE ALARM CONTROL PANEL., LIFE SAVING APPLIANCES: RESCUE BOAT ENGINE CAN NOT START, EMERGENCY SYSTEMS: EMERGENCY FIRE PUMP WATER PRESSURE LOW., ISM: ONLY 3/E, 2 AB HAVE MEDICAL CERTIFICATES., ISM: BECAUSE ITEM 1-30, SHOW SAFE MANAGEMENT NOT IMPLEMENT PROPERLY. ADDITIONAL AUDIT REQUIRED..

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.