

Ships Detained in Hong Kong due to PSC Inspection in February 2017

No.	IMO No.	Ship Name	Flag	YOB	GRT	Ship Type	Classification Society	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	8921664	PL YUI LAAM	Panama	1989	4025	Container	Korean Register of Shipping	Korean Register of Shipping/ Intermaritime Certification Services/Panama Maritime Documentation Services	Ocean Grow International Shipmanagement Consultant Corp	13.02.2017	08.03.2017	CERTIFICATE & DOCUMENTATION: THE SHIP DID NOT HAVE COMPETENCY 2ND ENGINEER ON BOARD AS PER MINIMUM SAFE MANNING CERT., RADIO COMMUNICATIONS: SHORE BASE MAINTENANCE SERVICE AGREEMENT FOR MAINTENANCE OF GMDSS EQUIPMENT WAS NOT VALID. AIS, EPIRB, VDR HAVE NOT BEEN SERVICED SINCE 16.12.2015. HYDROSTATIC RELEASE OF EPIRB EXPIRED., LIFE SAVING APPLIANCES: ANNUAL SERVICE OF PORT AND STARBOARD SIDE LIFE RAFTS HAVE NOT BEEN DONE AFTER DUE DATE. LAST SERVICE WAS ON 25.11.2016. HYDROSTATIC RELEASE OF LIFE RAFTS EXPIRED., LIFE SAVING APPLIANCES: FOOD RATION OF PORT AND STARBOARD LIFE BOAT EXPIRED., FIRE SAFETY: FIRE MAIN ON UPPER DECK PORT SIDE IN FRONT OF ACCOMMODATION WAS HEAVILY LEAKED.