## 海事處

船舶事務科

香港 中環 統一碼頭道38號 海港政府大樓24樓

電話號碼 : (852) 2852 4510 傳真號碼 : (852) 2545 0556

網站 Web Site: http://www.mardep.gov.hk 電郵地址 E-mail: ss\_css@mardep.gov.hk

貴署檔案 Your Ref.: ---

本處檔案 Our Ref.: MD-CSS-F02-040-04A-001



## MARINE DEPARTMENT

**Shipping Division** 

24/F., Harbour Building, 38 Pier Road, Central, Hong Kong

> Tel No: (852) 2852 4510 Fax No: (852) 2545 0556

> > 17 November 2022

## To: All Masters, Shipowners and Ship Managers of Hong Kong Registered Ships

Dear Sir/ Madam,

## 2021 Revised MARPOL Annex VI requirements on verification of attained EEXI and information of CII in SEEMP (Reminder)

Further to our circular letter issued on 17 August 2022, it is noted that there are still a large number of Hong Kong registered ships that have not submitted the details relating to the ship's operational CII to the Recognized Organizations (ROs).

- 2. We would like to reiterate that the verification of the ship's EEXI shall take place at the initial survey for new ships or at the first annual, intermediate or renewal survey for existing ships on or after 1 January 2023 according to regulation 5.4.7 in the 2021 Revised MARPOL Annex VI.
- 3. On or before 1 January 2023, Ship Energy Efficiency Management Plan (SEEMP) of the applicable ship shall include the details relating to the ship's operational CII, e.g. an implementation plan on how to achieve the required annual operational CII as specified in regulation 28 of the 2021 Revised MARPOL Annex VI.
- 4. To allow sufficient time to accommodate the above requirements, shipowners and ship managers are urged to contact the ROs authorized by this Department (<a href="https://www.mardep.gov.hk/en/faq/surveycs.html">https://www.mardep.gov.hk/en/faq/surveycs.html</a>) at the earliest opportunity in relation to EEXI and CII.
- 5. The provisions of Merchant Shipping (Prevention of Air Pollution) (Amendment) Regulation 2022 (<u>L.N.157 of 2022</u>) related to EEXI and CII will into operation on 1 January 2023. All Hong Kong registered ships are required to comply with the MARPOL Annex VI where applicable. Failure to comply with the said

regulation may result in port State control intervention.

6. Should you have any queries, please do not hesitate to contact us by email at ss\_css@mardep.gov.hk.

Yours faithfully,

(No signature on website)

(C. W. HO)
Senior Surveyor of Ship / Cargo Ships Safety Section
Shipping Division
for Director of Marine