Ships Detained in Hong Kong due to PSC Inspection in February 2017

N	o. 1	IMO No.	Ship Name	Flag	YOB	GRT	Ship Type	Classification Society	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
	1	8921664	PL YUI LAAM	Panama	1989	4025	Container	Korean Register of Shipping	Korean Register of Shipping/ Intermaritime Certification Services/Panama Maritime Documentation Services	Ocean Grow International Shipmanagement Consultant Corp	13.02.2017	08.03.2017	CERTIFICATE & DOCUMENTATION: THE SHIP DID NOT HAVE COMPETENCY 2ND ENGINEER ON BOARD AS PER MINIMUM SAFE MANNING CERT., RADIO COMMUNICATIONS: SHORE BASE MAINTENANCE SERVICE AGREEMENT FOR MAINTENANCE OF GMDSS EQUIPMENT WAS NOT VALID. AIS, EPIRB, VDR HAVE NOT BEEN SERVICED SINCE 16.12.2015. HYDROSTATIC RELEASE OF EPIRB EXPIRED., LIFE SAVING APPLIANCES: ANNUAL SERVICE OF PORT AND STARBOARD SIDE LIFE RAFTS HAVE NOT BEEN DONE AFTER DUE DATE. LAST SERVICE WAS ON 25.11.2016. HYDROSTATIC RELEASE OF LIFE RAFTS EXPIRED., LIFE SAVING APPLIANCES: FOOD RATION OF PORT AND STARBOARD LIFE BOAT EXPIRED., FIRE SAFETY: FIRE MAIN ON UPPER DECK PORT SIDE IN FRONT OF ACCOMMODATION WAS HEAVILY LEAKED.