

### Ships Detained in Hong Kong Due to PSC Inspection in Feburary 2021

No.	IMO No.	Ship Name	Flag	YOB	GRT	Ship Type	Classification society	Related ROs	Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9111591	ANA OCEAN	Sierra Leone	11.04.1995	15737	BULK CARRIER	FSC	FSC	FORWARD MARINE LIMITED	16.2.2021	23.2.2021	Self-activate of smoke signal for Man Overboard located at bridge wing (S) was found damaged; Fire hose in bridge wing (S) was found leakage seriously; Numerous of fire hose' nozzles in the fire hose box were found missing; Emergency generator was failed to start by second group of battery; Port side lifeboat engine was failed to start by second group of battery; and The deficiency items in the Report of Inspection (Form B) in related to SMS failed to ensure proper shipboard operation and maintenance in conformity.