

Ships Detained in Hong Kong Due to PSC Inspection in June 2022

No.	IMO No.	Ship Name	Flag	YOB	GRT	Ship Type	Classification society	Related ROs	Company	Date of Detention	Date of Release	Nature of Detainable Deficiencies (responsible RO, if any)
1	8810334	UEI MARU	Mongolia	01.05.1988	699	General cargo/multipurpose	Foresight Ship Classification (FSCLASS)	Foresight Ship Classification (FSCLASS)	DONGHAI SHIPPING CO. LIMITED	06.06.2022	24.06.2022	<ol style="list-style-type: none"> 1. Navigation and signal lights (Port side) were out of order on the navigation bridge mast. 2. The ship's fire detection system was inoperative and can't demonstrate the fire alarm testing. 3. Engine room forward ventilation head was inoperative. 4. Emergency generator was not available to use. 5. As per deficiencies on the PSC report (Form B), the SMS implemented onboard did not ensure effective maintenance of the ship and its equipment.