

Ships Detained in Hong Kong Due to PSC Inspection in January 2023

No.	IMO No.	Ship Name	Flag	Date of Keel Laid	GRT	Ship Type	Classification society	Related ROs	Company	Date of Detention	Date of Release	Nature of Detainable Deficiencies (responsible RO, if any)
1	8677287	AEGIS ELITE	Sierra Leone	16.05.2003	3844	General Cargo/Multipurpose	Asia Shipping Certification Services	Asia Shipping Certification Services	Tongcheng Shipping Co Ltd	11.01.2023	13.01.2023	1. Emergency fire pump is out of order; and 2. Oily water separator 15ppm alarm can't demonstrate to PSCO during the inspection
2	9506708	AIS SUN	Liberia	21.01.2009	33044	Bulk Carrier	DNV AS	DNV AS	INCHCAPE SHIPPING SERVICES (HK) LTD	13.01.2023	13.02.2023	1. Both sides accommodation ladders out of order, platforms were seriously corroded and holed; 2. Emergency fire pump was out of order; 3. Oil accumulation at steering gear room and three (3) DG generators area in engine room; 4. Assess hatch covers to all cargo holds, forecastle store room cannot be closed properly and cannot maintain watertight integrity, all sounding pipes for double bottom tanks and top side tanks on deck were found their covers missing or cannot be closed properly; and 5. The identified deficiencies shown that the ship ISM on maintenance of ship equipment failure.