

### Ships Detained in Hong Kong Due to PSC Inspection in December 2023

No.	IMO No.	Ship Name	Flag	Date of Keel Laid	GRT	Ship Type	Classification society	Related ROs	Company	Date of Detention	Date of Release	Nature of Detainable Deficiencies (responsible RO, if any)
1	8889555	RAMBLER STAR	Togo	02.11.1994	1478	General cargo/multipurpose	Universal Maritime Bureau Ltd	Universal Maritime Bureau Ltd	Hang Tat Container Warehouse Ltd	05.12.2023	-	1. Oily water separator is not working; 2. Fire detection system is not working; 3. Rescue boat engine is not working; 4. All Liferaft annual service report cannot be found and two hydrostatic release expired; 5. ISM/SMC implementation onboard was found failure and external ISM/SMC audit should be conducted by Recognized Organization;