

## Ships Detained in Hong Kong Due to PSC Inspection in May 2017

No.	IMO No.	Ship Name	Flag	YOB	GRT	Ship Type	Classification Society	Related ROs	Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9290218	MONTOK	Indonesia	2003	7320	General cargo/multi purpose	Nippon Kaiji Kyokai	Nippon Kaiji Kyokai/Biro Klasifikasi Indonesia	PT Pelayaran Andalas Bahtera Baruna	04.05.2017	10.05.2017	<b>POLLUTION PREVENTION:</b> THE SEWAGE OVERBOARD VALVE WAS PARTIALLY OPEN TO OVERBOARD AND STUCK, AND THE BLOWER OF SEWAGE TREATMENT PLANT WAS STOP., <b>ISM:</b> BASE ON THE DEFICIENCIES 1, 2, 5, 6, 8, 9, 13, ISM CODE PART A / 8 WAS NOT PROPERLY IMPLEMENTED., <b>ISM:</b> BASE ON THE DEFICIENCIES 15, 16, 17, 18, 19, 20, 21, 22, 23, ISM CODE PART A / 10 WAS NOT PROPERLY IMPLEMENTED..
2	8779891	LUCK OCEAN	*Tanzania	1999	992	Container ship	*Maritime Bureau of Africa	*Maritime Bureau of Africa/ Tanzania	Good Ever Co Ltd	09.05.2017	29.06.2017	<b>FIRE SAFETY:</b> ALL FIRE PUMPS MALFUNCTION, <b>STRUCTURAL CONDITIONS:</b> NO STABILITY INFORMATION BOOKLET ON BOARD, <b>CERTIFICATE &amp; DOCUMENTATION:</b> NO SOPEP ONBOARD, <b>LIFE SAVING APPLIANCES:</b> NO LIFEBOATS ON BOARD AS REQUIRED BY CARGO SHIP SAFETY EQUIPMENT CERTIFICATE (FORM E),
3	9531337	FOS GEMINI	Indonesia	2009	797	Offshore supply	American Bureau of Shipping	American Bureau of Shipping/Biro Klasifikasi Indonesia	FOS Management Services Pte Ltd	23.05.2017	26.05.2017	<b>CERTIFICATE &amp; DOCUMENTATION:</b> ON BOARD MANNING SHORT OF ONE RATING FOR ENGINE ROOM WATCH KEEPING, NOT MET REQUIREMENT OF MINIMUM SAFE MANNING CERTIFICATE FOR SIX MONTHS., <b>POLLUTION PREVENTION:</b> SEWAGE TREATMENT PLANT NOT FUNCTION AND TRIPPED., <b>ISM:</b> AS EVIDENCE OF DEFICIENCY NO.5, ISM / S6 NOT IMPLEMENTED EFFECTIVELY., <b>ISM:</b> AS EVIDENCE OF DEFICIENCY NO.14, ISM / S10 NOT IMPLEMENTED EFFECTIVELY..

\* At time of ship released from detention