

Ships Detained in Hong Kong Due to PSC Inspection in July 2019

No.	IMO No.	Ship Name	Flag	YOB	GRT	Ship Type	Classification society	Related ROs	Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	9119488	ERIN	Belize	1996	8944	General cargo / multipurpose	RINA Services S.p.A.	Intermaritime Certification Services, ICS Class; RINA Services S.p.A.; Universal Maritime Bureau Ltd	Kind Glory Shipping Co Ltd	22.07.2019	28.07.2019	<p>Labour Conditions - RANDOM CHECK ON CREW REST ROOM (OILER AND FITTER) THE WASHING BASIN IS MISSING. ALL FAN DAMPER MISSING. TOILET SEAT MISSING. SANITATION IN BAD CONDITION.</p> <p>Water/Weathertight conditions - WINDOW OF CREW LAUNDRY ROOM MISSING. WINDOW OF BOSUN REST ROOM MISSING</p> <p>Fire safety - ENGINE ROOM FAN DAMPER NOT ABLE TO FULLY CLOSED. GAP 2 CM</p> <p>Fire safety - EXCESSIVE OIL AT PURIFIER ROOM SAVEALL. EXCESSIVE OILY BILGE AT STEERING GEAR ROOM (30CM) IN DEPTH</p> <p>Alarms - ENGINE ROOM AFT BILGE HIGH LEVEL ALARM UNAUTHORIZED INSTALLATION</p>