

Ships Detained in Hong Kong Due to PSC Inspection in November 2023

No.	IMO No.	Ship Name	Flag	Date of Keel Laid	GRT	Ship Type	Classification society	Related ROs	Company	Date of Detention	Date of Release	Nature of Detainable Deficiencies (responsible RO, if any)
1	1022847	XIN MING*	Tanzania	08.06.2004	499	General cargo/multipurpose	Eagle Classification of Shipping	Eagle Classification of Shipping	YUNHAN INTERNATIONAL SHIP MANAGEMENT CO., LIMITED	14.11.2023	-	1. "Certificate of Competence" cannot be provided for Master & all Officers, all crew members do not hold flag state's endorsements; 2. There were no medical certificates for all crew members onboard; 3. The Navigation (STBD & PORT) Sidelights are broken and not arranged as per statutory requirement (such as the designated angle... etc.); 4. No record of fire alarm system test and the fire detection system is inoperative; 5. Multiple Fire Doors (including Engine Room & Accommodation) cannot perform fire-resisting division; 6. Fire pump / Emergency fire pump is not working; 7. Multiple valves on fire main line are inoperative; 8. Fire drill cannot be performed by crew. Fireman Outfit and Accessories are not available onboard; 9. Voyage & Passage Plan was not prepared for the last voyage from "Busan, Republic of Korea" to "Hong Kong, China"; 10. Valid Charts and Publication are not available onboard to support navigation; 11. Emergency Escape Trunk, the arrangement is not maintained for a safe means of passage, the escape door cannot perform fire-resisting division and blocked by obstacle; 12. Multiple punctures were found on bulwarks along the deck (such as the Forecastle, the area adjacent to PORT side of Accommodation Block ...etc.); 13. Radio Life-saving (Two-way VHF Radio Telephone) apparatus and batteries are not available onboard; and 14. MF/HF DSC Radio is not available onboard.

* The vessel "XIN MING" was found departing from Hong Kong Waters without permission on 17 November 2023. Notification has been sent to Tokyo MOU Secretariat.